

PDR RID Report

Originator Mike Rackley **Phone No** 286-2220
Organization FOS 510
E Mail Address mike.rackley@gsfc.nasa.gov
Document CSMS PDR

RID ID	PDR	224
Review	CSMS	
Originator Ref	FOS 002	
Priority	2	

Section	Page	Figure Table	Presentation
---------	------	--------------	--------------

Category Name Design-CSS

Actionee HAIS

Sub Category

Subcategory ID

Subject System timing source at EOC.

Description of Problem or Suggestion:

The EOC as proposed would be responsible for acting as the timing source for other ECS segments (DCE cells) such as the DAACs. The EOC should only be involved in activities that directly relate to supporting spacecraft operations.

Originator's Recommendation

Reevaluate using the EOC as a timing source. Consider a design that makes the non-EOC components of ECS independent of the EOC with respect to system timing.

GSFC Response by:

GSFC Response Date

HAIS Response by:

HAIS Schedule

HAIS R. E.

HAIS Response Date

Status	Date Closed	Sponsor	desJardins
---------------	--------------------	----------------	-------------------

***** Attachment if any *****
